Reynolds Equipment Co. LVC INFO 4-5-01

PROCEDURE FOR COVERTING PROFILER DATA TO EXCEL

1. Using the “Windows” LVCHost software version 4.11, connect to the LVC unit.
2. Download the “Profiler” file from the unit.
3. Select “Convert Flat File to CSV” from the “Tools” column.
4. Choose the file to print and click “Open”.
5. Choose the Start and End of the report/ OR just click “OK”/ which will select the default, which will include ALL data.
6. The Spreadsheet program (Excel is most common) will automatically run including the data selected.
7. Double-click between the “A” and “B” cells to automatically size the date and time.
8. Select the data to graph.
9. Click the “Graph” icon in Excel.
10. Follow the instructions to customize the graph.
11. If you need help using Excel, select “help” in Excel.

File: Procedure for CSV Data in New LVCHost.Doc